


TOSOT Parts Diagram



41	Cold Plasma Generator
40	Remote Controller
39	Connecting Cable
38	Connecting Cable
37	Power Cord
36	Electric Box Cover2
35	Screw Cover
34	Decorative Board (Right)
33	Terminal Board
32	Electric Box Cover
31	Shield Cover of Electric Box
30	Main Board
29	Jumper
28	Electric Box
27	Lower Shield of Electric Box
26	Electric Box Assy
25	Drainage hose
24	Stepping Motor
23	Crank
22	Connecting pipe clamp
21	Wall Mounting Frame
20	Motor Press Plate
19	Fan Motor
18	Cross Flow Fan
17	Evaporator Assy
16	Evaporator Support
15	Ring of Bearing
14	O-Gasket sub-assy of Bearing
13	Rubber Plug (Water Tray)
12	Rear Case assy
11	Left Axle Bush
10	Helicoid tongue
9	Air Louver
8	Axle Bush
7	Guide Louver
6	Front Case
5	Decorative Board (Left)
4	Filter Sub-Assy
3	Display Board
2	Front Panel
1	Decorative Strip